

HAER
CAL
22-YOSEM,
19-

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

TENAYA CREEK BRIDGE

HAER No. CA-98

Yosemite National Park Roads and Bridges
Spanning Tenaya Creek on Mirror Lake Road
Yosemite National Park
Mariposa County
California

Brian C. Grogan, photographer, summer 1991

- CA-98-1 VIEW OF EAST FACE AND ARCH FROM SOUTH BANK.
- CA-98-2 RETAINING WALL AT SE CORNER OF BRIDGE. SITE OF OLD GAUGING STATION.
- CA-98-3 VIEW NORTH ALONG TENAYA CREEK AT EAST FACE OF BRIDGE.
- CA-98-4 CONSTRUCTION DETAILS, UNDERSIDE OF ARCH FACING SW CORNER.
- CA-98-5 US GEOLOGICAL SURVEY MARKER AT OLD GAUGING STATION SITE.
- CA-98-6 UNDERSIDE OF ARCH, CONSTRUCTION DETAILS NE CORNER.
- CA-98-7 REMAINS OF OLD GAUGING STATION WITH BRIDGE IN BACKGROUND.
- CA-98-8 ROCK WORK AND CONSTRUCTION DETAILS, SE CORNER.
- CA-98-9 CONCRETE FOOTING, ROCK DETAIL AND STRESS FRACTURE AT SW CORNER.
- CA-98-10 CONSTRUCTION DETAIL, SE CORNER OF ARCH.
- CA-98-11 CURB STONES, SIDEWALK AND WALL WITH BRIDGE SIGN.
- CA-98-12 WALL AND EROSION IN BRIDAL PATH.